

Menu

HISTORY FILE MAP for year 1999


Realtime

Playback

Recalled Realtime

Recalled Playback

10m data gap - TGC problems at DSS42 during BRC from 1024 to 512bps. DR A03983 refers.



10m data gap - TGC problems at DSS42 during BRC from 2048 to 512bps. DR A03988 refers.

9m RT data lost at DSS43 - problems with s/c transition from 2-way to 1-way followed by bitrate change from 1024 to 512bps. No DR.

55m RT 4K plus 5h26m PB 512bps data lost due to ASC (Antenna Sub-assembly Controller) failure at DSS14. DR G05280 refers.